## TOP SECRET

OUT 51532

2 4 JUL 1963

CJS

1963 JUL 232256Z

T	0	Р	S	E	С	R	E	T	232244	4Z

REF MSN 9056 FTV 1166

SUBJ: DATA BLOCK MALFUNCTIONS

- NO PINARY CLOCK DATA WAS RECORDED ON THE FILM FOR SEVERAL HUNDRED FRAMES, PRIMARILY ON THE FWD CAMERA. OCCURRED INTERMITTENTLY THROUGHOUT THE MISSION.
- Grace (File) THE FLARE PROBLEM ENCOUNTERED ON THE FWD CAMERA WASHED OUT ALL OR PART OF THE DATA BLOCK ON MANY FRAMES.
- AFTER PASS 4 D THE CAMERA NUMBER AND RELATED INDEX BIT WERE MISSING. BOTH FWD AND AFT.
- 4. GREATEST DIFFICULTY OCCURED WITH THE FWD CAMERA ON PASSES D 25, D 37, D 38, D 40 AND D 55. IN EACH OF THESE PASSES ABOUT ONE THIRD OF THE BINARY BLOCKS WERE MISSING.
- THESE MALFUNCTIONS MADE MACHINE READING IMPOSSIBLE, NECESSITATING MANY MAN-HOURS OF EXTRA WORK AND REDUCED ACCURACY DUE TO THE MANY INTERPOLATIONS THAT HAD TO BE MADE. TOPSECRET

END OF	四たSSAGE
--------	---------

Declassification Review by NGA/DoD

> GROUP 1 Excluded from automat downgrading and leclassification

25X1